

## State of Utah

## Department of Natural Resources

MICHAEL R. STYLER Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:		
Company	y Jay Marshall Resident Agent		
OGM	Pete Hess Environmental Scientist III		

# **Inspection Report**

Permit Number:	C0070013
Inspection Type:	PARTIAL
Inspection Date:	Thursday, January 29, 2009
Start Date/Time:	1/29/2009 8:25:00 AM
End Date/Time:	1/29/2009 11:15:00 AM
Last Inspection:	Wednesday, January 21, 2009

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear, cold; 20's F.

InspectionID Report Number: 1901

Accepted by: jhelfric

2/23/2009

Permitee: UTAHAMERICAN ENERGY INC

Operator: UTAHAMERICAN ENERGY INC

Address: PO BOX 986, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Site: HORSE CANYON MINE

Permit Status: ACTIVE

**Current Acreages** 

## Mineral Ownership

#### **Types of Operations**

5,992.07	<b>Total Permitted</b>	✓ Federal	<b>✓</b> Underground
99.56	<b>Total Disturbed</b>	<b>✓</b> State	Surface
61.65	Phase I	✓ County	☐ Loadout
	Phase II	<b>✓</b> Fee	Processing
	Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Construction activities continue at the Lila Canyon site.

Most of the snow at the site has melted into the ground. There were no flows observed in any of the channels.

Inspector's Signature:

**Date** 

Thursday, January 29, 2009

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Permit Number: C0070013 Inspection Type: PARTIAL

Inspection Date: Thursday, January 29, 2009

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil	<b>✓</b>		<b>✓</b>	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	<b>✓</b>		<b>✓</b>	
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		<b>✓</b>		
8.	Noncoal Waste	<b>✓</b>			
9.	Protection of Fish, Wildlife and Related Environmental Issues	<b>✓</b>		✓	
10.	Slides and Other Damage		<b>✓</b>		
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation	. []			
14.	Subsidence Control		<b>✓</b>		
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing	✓			
16.t	Po Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		<b>✓</b>	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance	<b>V</b>		<b>✓</b>	
22.	Other				

Permit Number: C0070013 Inspection Type: PARTIAL

Inspection Date: Thursday, January 29, 2009

Page 3 of 3

## 3. Topsoil

A dozer was working the topsoil storage area during the inspection.

#### 5. Explosives

The Permittee has set off 1/2 of an explosive round in the #1 tunnel (January 26, 2009). All entries are being developed uphill and on a horizontal angle less than 90 degrees. Thus, a partial face must be developed to square the face of the entry. The tying in of the protective canopy to the rock face in the #1 entry is still happening. A canopy has been set at the #2 face, but tying in of the metal to the rock has yet to be started. Face #3 has been trimmed and marked for drilling, but, to date, no canopy has been set. Mr. Bodee Allred is the Utah certified coal mine surface blaster (recertification completed on January 16, 2009). The blasting record for the January 26th shot was reviewed. As noted, a full face was not loaded.

# 9. Protection of Fish, Wildlife and Related Environmental Issues

The Permittee's contractor performed an evaluation for raptors over and adjacent to the Lila construction area on January 27, 2009. No raptors were observed in flight during today's inspection.

## 18. Support Facilities, Utility Installations

The Permittee's construction contractor has made significant progress in developing this site. The main office / bath house pad area appears ready to receive temporary facilities which are currently located at the terminus of Emery County road 126. This site is difficult to develop because of the amount of boulders buried sub-surface. Numerous track mounted hydraulic hammers are being utilized to reduce the boulders to sizes for ease of handling. All boulder material is sandstone. The run-of-mine coal stockpile pad and the shop / warehouse pad are also being developed at this time. An electrical substation is being constructed by BODEC Electric adjacent to the UP & L line below the site. Further investigation needs to occur relative to ownership / permitting requirements (I.e., raptor protection, R645-301-358.510).

#### 21. Bonding and Insurance

The Division notified the Permittee on October 8, 2008 that the Best Rating for the Lincoln General Insurance Company (surety for the Horse Canyon Mine permit area "A" bond in the amount of \$1,061,328) was a B+. According to R645-301-860.110, the Best Rating for a surety must be at least an A-. The Permittee has been given until February 9, 2009 to respond to this bonding requirement. A Phase III bond release application has been filed with the Division for the permit area "A" / Geneva Mine area. A field inspection of the site was conducted with various government agencies attending (OSM) on December 8, 2008. The Division has responded with a deficiency document dated January 20, 2009.